





# 2017 Encore E Replacement Parts and Pricing



# Steering Parts

| Assembly Part | Includes  | Description                             | Qty      | Retail Each      | Retail Total     |
|---------------|-----------|---|----------|------------------|------------------|
| <b>STE201</b> |           | <b>Steering Assembly – Encore E</b>     | <b>1</b> | <b>\$ 375.00</b> | <b>\$ 375.00</b> |
|               | STE602ASY | Steering Handle Assembly (see next pgs) | 1        | \$ 50.00         | \$ 50.00         |
|               | STE604    | Rudder                                  | 1        | \$ 90.00         | \$ 90.00         |
|               | STE612PEX | Tubing – 3/4" x 5/8" PEX                | 7 ft     | \$ 30.00         | \$ 30.00         |
|               | FAS808    | Washer 3/8 x .875 SS                    | 2        | \$ 1.00          | \$ 2.00          |
|               | STE629    | Rudder Lever - Single (Encore E)        | 1        | \$ 30.00         | \$ 30.00         |
|               | STE622    | Steering tube clamp- Bottom             | 2        | \$ 5.00          | \$ 10.00         |
|               | PLN019    | Steering tube clamp - Top               | 2        | \$ 2.00          | \$ 4.00          |
|               | STE618    | Steering Rod, 1/2" Acetal               | 1        | \$ 50.00         | \$ 50.00         |
|               | FAS381    | BHCS 3/8-16 x 3/4 SS                    | 2        | \$ 2.00          | \$ 4.00          |
|               | FAS248    | PHPB #14 x 1.0 SS                       | 4        | \$ 1.00          | \$ 4.00          |
|               | STE623    | Take-up Clip (Steering Rod)             | 2        | \$ 2.00          | \$ 4.00          |
|               | DRS501    | Spoke Knob – 1/2 " Bolt                 | 1        | \$ 5.00          | \$ 5.00          |
|               | FAN508    | HHCS 1/2 -13 x 1.50 NYB                 | 1        | \$ 2.00          | \$ 2.00          |
|               | STE621    | Pivot Link (Steering)                   | 1        | \$ 3.00          | \$ 3.00          |
|               | STE625    | Pivot Link - Clip Type                  | 1        | \$ 4.00          | \$ 4.00          |
|               | STE626    | C- Clip                                 | 2        | \$ 1.00          | \$ 2.00          |
|               |           | <i>Not part of above assembly:</i>      |          |                  |                  |
|               | PLN022    | Rudder Bushing, Upper                   | 1        | \$ 5.00          | \$ 5.00          |
|               | PLN023    | Rudder Bushing, Lower                   | 1        | \$ 5.00          | \$ 5.00          |







## Steering Handle Assembly

| Assembly Part    | Includes | Description                     | Qty      | Retail Each     | Retail Total    |
|------------------|----------|---------------------------------|----------|-----------------|-----------------|
| <b>STE602ASY</b> |          | <b>Steering Handle Assembly</b> | <b>1</b> | <b>\$ 50.00</b> | <b>\$ 50.00</b> |
|                  | STE602   | Steering Handle                 | 1        | \$ 30.00        | \$ 30.00        |
|                  | STE616   | Adjuster-Steering Handle        | 2        | \$ 5.00         | \$ 10.00        |
|                  | FAS383   | BHCS 3/8-16 x 1 1/4 SS          | 2        | \$ 2.50         | \$ 5.00         |
|                  | FAN359   | SHCS 3/8-16 x 3/4 NY            | 2        | \$ 2.00         | \$ 4.00         |
|                  | FAS385   | BHCS 3/8-16 x 1 1/2 SS          | 1        | \$ 3.00         | \$ 3.00         |
|                  | FAS808   | Washer 3/8 x .875 SS            | 1        | \$ 1.00         | \$ 1.00         |
|                  | PLN052   | Retainer (Steering Handle)      | 1        | \$ 7.50         | \$ 7.50         |
|                  | STE614   | Hole Plug, 1 1/4" NYB           | 1        | \$ 1.00         | \$ 1.00         |

Back side of steering handle




Front side of steering handle




# Electric Option

| Assembly Part | Includes | Description  | Qty      | Retail Each       | Retail Total      |
|---------------|----------|--|----------|-------------------|-------------------|
| <b>ELE902</b> |          | <b>ELECTRIC ASSEMBLY COMPLETE</b>                    | <b>1</b> | <b>\$ 1500.00</b> | <b>\$ 1500.00</b> |
|               | ELE900   | Motor assembly Enc P/E, E                            | 1        | \$ 1000.00        | \$ 1000.00        |
|               | ELE901   | Wiring Assembly*                                     | 1        | \$ 200.00         | \$ 200.00         |
|               | ELE138   | Charger - ProSport 6 3-stage waterproof marine       | 1        | \$ 110.00         | \$ 110.00         |
|               | ELE134   | LED Battery Meter                                    | 1        | \$ 35.00          | \$ 35.00          |
|               | ELE136   | Master Battery Switch                                | 1        | \$ 45.00          | \$ 45.00          |
|               | ELE176   | Circuit Breaker 60 amp Manual reset                  | 1        | \$ 85.00          | \$ 85.00          |
|               | SEA609   | Standoff-Spacer 1.0" x .75                           | 6        | \$ 1.25           | \$ 7.50           |
|               | FAS202   | PPMS 1/4-20 x .625 SS                                | 6        | \$ 0.75           | \$ 4.50           |
|               |          | <i>*contact Nauticraft for specific items needed</i> |          |                   |                   |





| Assembly Part | Includes  | Description                           | Qty      | Retail Each       | Retail Total      |
|---------------|-----------|---------------------------------------|----------|-------------------|-------------------|
| <b>ELE900</b> |           | <b>Motor Assembly, Enc P/E, E</b>     | <b>1</b> | <b>\$ 1000.00</b> | <b>\$ 1000.00</b> |
|               | ELE223    | Motor - Minn Kota electric salt water | 1        | \$ 650.00         | \$ 650.00         |
|               | ELE101BLK | Motor Mount-Top, Black                | 1        | \$ 20.00          | \$ 20.00          |
|               | ELE102BLK | Motor Mount-Bottom, Black             | 1        | \$ 25.00          | \$ 25.00          |
|               | FAS385    | BHCS 3/8-16 x 1- 1/2 SS               | 6        | \$ 3.00           | \$ 18.00          |
|               | FAS808    | Washer 3/8 x .875 SS                  | 8        | \$ 1.00           | \$ 8.00           |
|               | ELE103    | Motor mount spacer 3/4" x 4.0         | 4        | \$ 5.00           | \$ 20.00          |
|               | FAS385    | BHCS 3/8-16 x 1- 1/2 SS               | 8        | \$ 3.00           | \$ 24.00          |
|               | FAS252    | THPA # 14 x 1" SS                     | 6        | \$ 0.50           | \$ 3.00           |



# Seat and Covers

| Assembly Part    | Includes  | Description   | Qty      | Retail Each      | Retail Total     |
|------------------|-----------|---|----------|------------------|------------------|
| <b>SEA101GEN</b> |           | <b>Operators Seat Assembly, Available in Red or Turquoise</b> | <b>2</b> | <b>\$ 375.00</b> | <b>\$ 750.00</b> |
|                  | SEA510GEN | COVER, Operator's Seat Cushion (Cherry (red) or Turquoise)    | 1        | \$ 150.00        | \$ 150.00        |
|                  | SEA512    | FOAM, Operator's Seat, 1 ½"                                   | 1        | \$ 75.00         | \$ 75.00         |
|                  | SEA501    | Seat (shell)  | 1        | \$ 125.00        | \$ 125.00        |
|                  | FAS171    | OHPA 10 x ¾" SS   | 14       | \$ 0.50          | \$ 7.00          |
|                  | SEA521    | Seat Adjust Lever   | 1        | \$ 45.00         | \$ 45.00         |
|                  | SEA522    | Knob (Seat Lever)   | 1        | \$ 5.00          | \$ 5.00          |
|                  | FAS237    | FPMS ¼ - 20 x1.50 SS  | 1        | \$ 2.00          | \$ 2.00          |
|                  | FAN523    | SHCS ½ - 13 x 1" NY   | 2        | \$ 2.00          | \$ 4.00          |
|                  | FAN525    | SHCS ½ - 13 x 1.5 NY  | 4        | \$ 2.00          | \$ 8.00          |
|                  | PLN049    | Spacer (Seat Retainer)  | 4        | \$ 2.00          | \$ 8.00          |
|                  | DRS503    | Washer - ½ x 2.25   | 4        | \$ 2.50          | \$ 10.00         |
|                  |           | <b>Stern/Bow Cushions, Red or Turquoise</b>                   |          |                  |                  |
| SEA604           |           | FOAM Bow Cushion (Enc)  | 1        | \$ 60.00         | \$ 60.00         |
| SEA602           |           | FOAM Stern Cushion (Enc)                                      | 1        | \$ 60.00         | \$ 60.00         |
| SEA605GEN        |           | COVER Bow Cushion (Enc) (Cherry (red) or Turquoise)           | 1        | \$ 120.00        | \$ 120.00        |
| SEA603GEN        |           | COVER Stern Cushion (Enc) (Cherry (red) or Turquoise)         | 1        | \$ 100.00        | \$ 100.00        |
| SEA601           |           | Storage Compartment Cover (Enc) Stern or Bow                  | 2        | \$ 60.00         | \$ 120.00        |






SEA501



SEA512

SEA510GEN



SEA605GEN w/  
SEA604

SEA603GEN w/  
SEA602

## Miscellaneous Parts

| Part               | Description                 | Retail each |
|--------------------|-----------------------------|-------------|
| HUL419             | Deck Plate – 5" white       | \$ 12.00    |
| HUL420             | Deck Plate – 6" white       | \$ 15.00    |
| HUL503             | Windshield, Encore          | \$ 150.00   |
| HUL430             | Windshield Trim             | \$ 10.00    |
| FAS175             | PHPB #8 x 1/2" SS           | \$ 0.25     |
| HUL504             | Full Floorboards (Encore E) | \$ 125.00   |
| FAS381<br>w/HUL457 | Drain Plug with O-ring      | \$ 3.00     |